

VILLAGE OF TUXEDO PARK
80 LORILLARD ROAD
TUXEDO PARK, NEW YORK 10987

DPW Report
April 17, 2024 to May 21, 2024

DPW

1. Mowed grass throughout the Village
2. Cleaned out and organized storage sheds at Wee Wah Park
3. Power washed boathouse at Wee Wah Park
4. Made new concrete anchors for the raft and rope system at Wee Wah Park
5. Installed new sign at the entrance to Wee Wah Park
6. Adjusted and secured roadside mirror on East Lake Road
7. Weed-whacked Pond 3 and Wee Wah Dam embankments
8. Repaired a window shutter at the Village Office
9. Installed a 12" rain pipe at the Mountain Farm Pump station and re-graded driveway
10. Cleared a clogged rain pipe at the end of Brook Road
11. Regraded part of the access road to the Mountain Farm storage tank
12. Cut back brush along fence line at the Sewer Plant
13. Cut brush at the base of the Pond 3 Dam to inspect leak
14. Worked with Nelson Tree Service removing tree on West Lake Road
15. Patched potholes on West Lake Road
16. Removed metal debris from the Cliff Road trail
17. Replaced wood decking on DPW roller trailer, also scraped and repainted
18. Worked with Sterling Carting on bulk pickup
19. Met with engineers in regard to Pond 3 Dam leakage
20. Loaded dumpster with scrap metal; received check for \$244.20
21. Steam-cleaned boats

Water and Sewer

1. Painted fire hydrants on East Lake Road and Ridge Road
2. Finished hydrant flushing on April 23rd
3. Did various water and sewer mark-outs for Dig Safe NY
4. Repaired concrete ceiling at the Water Plant
5. Did weekly meter readings on Village accounts
6. Obtained various meter readings requested by Denise Spalthoff
7. Continued weekend and holiday water and sewer operations
8. Installed water meter at the Wee Wah Park and opened bathhouse
9. Installed seasonal water meters
10. Installed a new crane arm and winch system at the Sewer Plant
11. Found a small leak at the base of storage tank on Ridge Road; John Ledwith contacted tank company to come and inspect both tanks
12. Cleaned a clogged chemical line at the Water Plant
13. Repaired malfunctioning meters
14. Installed irrigation meters