

VILLAGE OF TUXEDO PARK
80 LORILLARD ROAD
P.O. BOX 31
TUXEDO PARK, NEW YORK 10987

DPW Report

October 22, 2020 – November 16, 2020

Water

1. Repaired 8" water main and added an 8" valve on Tuxedo Road.
2. Removed seasonal water meters.
3. Did monthly water samples.
4. Received chemical shipments.
5. Hach company serviced and calibrated chlorine analyzers and turbidimeters.
6. Did various water meter readings.
7. Greased pumps and motors at Water Plant.
8. Turned heat on in all pump houses.

Sewer

1. Did daily maintenance at sewer plant.
2. Greased all pumps and motors.
3. Had flow meters calibrated.
4. Had sludge removed from digesters.
5. Cleared sewer blockages on Stable Road, Lorillard Road.
6. Prepared and sent in Monthly Sewer report to DEC.
7. Flushed and cleared roots from sewer main on West Lake Stable Road by Pond #3.
8. Had chlorine analyzer serviced and calibrated.

Roads

1. Repaired guide rails on Tuxedo Road and West Lake Road.
2. Cut grass throughout the Village.
3. Started picking up leaves.
4. Cleaned drains and catch basins.
5. Removed debris screen from Wee Wah Dam and lowered lake to winter elevation.
6. Blacktopped Tuxedo Road at water main break site.
7. Installed new door at the DPW.
8. Installed sander on one truck.