

VILLAGE OF TUXEDO PARK
P.O. BOX 31
80 LORILLARD ROAD
TUXEDO PARK, NEW YORK 10987

DPW Report
May 15, 2018 to June 18, 2018

Roads

1. Cleaned up trees, branches and storm drains after severe storm on 5-15-18.
2. Worked with Nelson Tree Service (O&R) on tree removals.
3. Worked with Sterling Carting during bulk pick up.
4. Repaired damaged railing at Sonne boathouse. Winter damage.
5. Drained and removed all sand media from filter #2 at the water plant.
6. Cut grass and weed wacked throughout the Village.
7. Cut large area of high grass at the Race Track (6 hours).
8. Started sweeping Village roads.
9. Cleared trees and underbrush in an area between Tuxedo Road and Nursery Road (2 men, 6 hours = 12 hours).
10. Planted trees and shrubs, mulched around trees and shrubs, and spread wild flower seeds in the area between Tuxedo Road and Nursery Road (3 men, 8 hours = 24 hours).
11. Worked on water main break on West Lake Road.
12. Replaced 12" drain on Wee Wah Road at entrance to the Shore house.
13. Patched potholes on West Lake Road from South Gate along lake.
14. Patched holes at the DPW, Wee Wah Road and Tuxedo Road.
15. Cleaned up around DPW shop. Took 2 loads of scrap metal to Action Metal.
16. Cut down 4 dead trees by the DPW shop.
17. Placed a large boulder, installed a stone bench, finished placing remaining rip rap at drain outlets, and installed a catch basin frame and grate at the Race Track.

Water

1. Installed all seasonal meters.
2. Removed media from filter bed #1. Getting ready for paint.
3. Fixed water main break on West Lake Road.
4. Did daily maintenance and testing at water plant.
5. Made chemicals as needed.
6. Took bi-monthly water samples for O.C.H.D.
7. Changed out weekly charts.
8. Regularly checked Mt. Farm pump station and pressure regulator in Town.
9. Did five hydrant pressure tests for McGoey, Hauser and Edsall on Lower Continental Road.
10. Started reading water meters in the Village.
11. Received chemical shipments.
12. Removed low lift pump #1 pump. Stopped working.

Sewer

1. Regularly checked Turtle Point Road sewer pump station.
2. Prepared monthly sewer reports for the D.E.C.
3. Took bi-monthly sewer samples for the D.E.C.
4. Removed sludge from sewer plant.
5. Did daily testing and maintenance at sewer plant.
6. Steam cleaned trailers and boats.